


# ACCESSORIES FOR TEST FIXTURES


## Interface Pins

Brass, gold plated (rhodanized)


I-G1  
10,0 Ampere




I-G1S1  
10,0 Ampere




I-G1S2  
10,0 Ampere




I-G1S3  
10,0 Ampere




I-P18WR/0.8  
10,0 Ampere




I-Z1  
10,0 Ampere




I-Z1WR/0.8  
10,0 Ampere




I-P1S4  
10,0 Ampere




I-D32WW/12  
10,0 Ampere




I-C22WW/2  
10,0 Ampere



I-D22WW/2  
10,0 Ampere



I-D23WW/3  
10,0 Ampere




# ACCESSORIES FOR TEST FIXTURES


## Interface Pins

Brass, gold plated (rhodanized)


I-P1  
30,0 Ampere




I-P16LA/0.9  
30,0 Ampere




I-P20LA/2.5  
30,0 Ampere




I-P152  
40,0 Ampere




I-Z152  
15,0 Ampere




I-D19S1/2  
15,0 Ampere



I-C17LA/2  
20,0 Ampere



I-C18LA/3  
20,0 Ampere



I-D17LA/2  
20,0 Ampere

